

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

**2011 Chevrolet G1500 Vans AWD Wagon Express**

<b>VIN</b>	1GNSHCF4XB1153258		
<b>Ext. Color</b>	Blue		
<b>Int. Color</b>	Gray	<b>Interior</b>	Cloth
<b>Mileage</b>	71,157 <b>Actual Miles</b>		
<b>Engine</b>	5.3L 8-Cylinder Gas		
<b>Transmission</b>	Automatic		



## Auction Data

<b>Sale Date</b>	To Be Announced		
<b>Run #</b>	To Be Announced	<b>Inv #</b>	9081
<b>Consignor</b>	GSA FLEET SERVICES		

## Declarations

<b>Warranty</b>	GSA Regular Terms
<b>Mileage</b>	71,157 <b>Actual Miles</b>
<b>Title</b>	Clear Title

## Equipment

- All Wheel Drive
- Automatic Transmission
- 8 Cylinder Gas
- Air Conditioning
- Aux Power Outlets
- Rear Air Conditioning
- Third Row Seat
- 8 Passenger
- Anti-Theft System
- Electronic Traction Control
- Power Windows
- Power Locks
- Trip Counter
- Floor Mats
- Dual and Side Air Bags
- Cruise Control
- Anti Lock Brakes
- Air Bag
- Dual Air Bag
- Tilt Steering Wheel
- AM/FM CD
- Keyless Entry
- Hard Top
- Tinted Windows
- Power Steering
- Power Brakes
- Electric Mirrors
- Side Air Bags
- Rear Heater

## Damage Descriptions (CR completed on 11/3/2014 by Nick Scotton)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
<b>Front</b>									
1	Hood	Chipped	Visible On Close Inspection						--
<b>Front Subtotal</b>				--	--	--	--	--	--
						--	--	--	--

# 2011 Chevrolet G1500 Vans AWD Wagon Express

VIN: 1GNSHCF4XB1153258

Inv#: 9081

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

## Interior

2	Carpets	Dirty	Multiple Instances						--
									--

3	Seats	Stained	Multiple Instances						--
									--

### Interior Subtotal

--	--	--	--	--	--	--

## Left

4	Exterior Left	Light Scratch	Multiple Instances						--
									--

### Left Subtotal

--	--	--	--	--	--	--

## Mechanical

5	Engine	Checked - Ok	None						--
									--

6	Odometer	Checked - Ok	None						--
									--

7	Transmission	Checked - Ok	None						--
									--

### Mechanical Subtotal

--	--	--	--	--	--	--

## Rear

8	Exterior Rear	Light Scratch	Multiple Instances						--
									--

### Rear Subtotal

--	--	--	--	--	--	--

## Right

9	Exterior Right	Light Scratch	Multiple Instances						--
									--

### Right Subtotal

--	--	--	--	--	--	--

## Structural

10	Frame	Checked - Ok	None						--
									--

### Structural Subtotal

--	--	--	--	--	--	--

# 2011 Chevrolet G1500 Vans AWD Wagon Express

VIN: 1GNSHCF4XB1153258

Inv#: 9081

Total

--	--	--	--	--	--
		--	--	--	--

## Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)
Spare	MATCHED	/-	Average (Average)

## Miscellaneous

Coolant level	OK
Fuel level	3/4
Interior odor	OK
Oil level	OK
Transmission fluid level	OK


## Images



2011 Chevrolet G1500 Vans AWD Wagon Express

VIN: 1GNSHCF4XB1153258

Inv#: 9081



## 2011 Chevrolet G1500 Vans AWD Wagon Express

VIN: 1GNSHCF4XB1153258

Inv#: 9081

